

Aug 28 00 04:40p

Virginia Johnson

(415) 883-9411

p. 1




FIG. I




FIG. 2




FIG. 3

Aug 28 00 04:41p

Virginia Johnson

(415) 883-9411

p.2

10002260 " 00 Signs




FIG. 4





FIG. 5



Aug 28 00 04:41p

Virginia Johnson

(415) 883-9411

P. 3

卷之三




FIG. 6




FIG. 7




FIG. 8

00000000 00000000 00000000 00000000

Light Guard Systems Report Generator
Location: 1500 Santa Rose Blvd Last Report 931201
Date: Sat 15, 1993
Activity: Last 24 hours
1100 - 1115 E=25 W=32
1115 - 1130 E=20 W=10
<hr/>
1400 - 1415 E=37 W=12
System Status: Normal + + + No faults detected.
Current Battery condition: +13.1 CHARGED
End Report.....

40

FIG. 9




FIG. 10